

Weights	6 PCS
Weight Axis	1 PC
Cross Testing Table	1 PC
Thin Specimen Testing Table	1 PC
Fork-Shaped Testing Table	1 PC
Fine Wire Testing Table	1 PC
Screw Drivers	2 PCS
Horizontal Regulating Screws	4 PCS
Level	1 PC
Power Cord	1 PC
Eyepiece	1 PC
Vickers Hardness Blocks	2 PCS (one middle-sized HV0.2 block and one high-sized HV1 block)
Prepare Fuses (1A)	2 PCS
The USAGE Instruction Manual	1 PC