

## Certificate of Analysis

BASF (Thai) Ltd.

Please note that the certificates of analysis are also conveniently available or your BASF online portal.

2021-11-12 BASF Thai pichit.tongsri@basf.com +66 3845 6100 142 Certificate No 742 Page 2 of 2

## Inspection Certificate 3.1 according to EN 10204

Lutensol® TO 8

190KG Steel drums
Purchase Order/Customer Product#
P O NO IMP 023
00000000051434684

 Material
 51434684

 Order
 6009788922-000020

 Delivery
 6210810434-000020

 Lot
 M210820881

 Lot/Qty
 3040.000-KG

 Total
 7600.000-KG

 Transport
 000000000010/2/00706

Manufacturing Location: TH, 20000 Chonburi, 700/348 Bangna-Trad Km 57, Muang

Characteristic Method	Unit	Value	Lower Limit	Upper Limit
Color		0		30
EN 1557, 70*C pH (5% Aq.) @25*C		7.1	5.0	8.0
EN 1262, solution B Cloud point		59.5	58.0	62.0
EN 1890, method E Packing-/Productiondate Expiration date, shelf life		20.08.202		

The above results are means of individual test values determined on samples taken during production of the lot.

For BASF India Limited

Authorised Signatory

The aforementioned data shall constitute the agreed contractual quality of the product at the time of passing of risk. The data are controlled at regular intervals as part of our quality assurance program. Neither these data nor the properties of product specimens shall imply any legally binding guarantee of certain properties or of fitness for a specific purpose. No liability of ours can be derived therefrom.